

JETFLOCK

Material for ink-jet printing using sublimation inks

Description	Polyester Flock material for ink-jet printing using sublimation inks
Tips	Time and temperature are just indicative. Kindly follows instructions for the sublimation of inks used
Application instructions	<ol style="list-style-type: none"> 1)Print and cut 2)Remove images from polyester backing 3)Cover with a silicon treated paper 4)Heat apply <p>Due to the many different base materials available on the market, the following heat transfer instructions are given as guideline only:</p>
Temperature:	185°C
Time:	20 sec.
Pressure:	minimum
Washable to:	up to 90°C

SIZES AND COLOURS

ROLLS	width 1,50 m.	length 25 m.
	width 0,50 m.	length 25 m.
COLOURS	white	